SECTION.....PLACE.....

13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31

No. of days present	FEES Rs. Ps.	Date of payment

Name of work:- Annual maintenance of borewells in 110 villages areas of ward NO-04, Attur yelahanka Satellite Town Sub division.

Name of Agency:- SRI PRADEEPA K.A
NO:34, Seemappa Garden
Vinayaka Nagara, Vidyaranyapura post,
Bangalore-560097.

Job Number :- 004-23-000012

Estimate Cost RS:- 20.00 Lakhs

No. of Working days | Average attendance during the month | No. on roll during month

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE:.....

SECTION.....PLACE.....

FOR THE MONTH OF..SEPTEMBER..2022

Sl. No.	Admission No.	NAMES	1 2 3 4 5 6 7 8 9 10 11 12	13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31	No. of days present	FEES Rs. Ps.	Date of payment
		6 Transportation of pumping machinery	→ 1 - - - - -	- 1 - - - - - - - 1 - - - - - - -	3		
		7 labour charges.	→ 1 - - - - -	- 1 - - - - - - - 1 - - - - - - -	3		
		8 Repairs to motors.	→ 1 - - - - -	- - 1 - - - - - - - 1 - - - - - -	3		
		9 Replacement of motor parts.	→ - 1 - - - -	- - 1 - - - - - - - 1 - - - - - -	3		
		10 Rotor (with one year Guarantee)	→ - 1 - - - -	- - 1 - - - - - - - 1 - - - - - -	3		
		11 upper flange	→ - 1 - - - -	- - - 1 - - - - - - - 1 - - - - -	3		
		12 Lower flange	→ - 1 - - - -	- - - 1 - - - - - - - 1 - - - - -	3		
		13 upper Housing	→ - - 1 - - -	- - - 1 - - - - - - - 1 - - - - -	3		
		14 Lower Housing	→ - - 1 - - -	- - - - 1 - - - - - - - 1 - - - -	3		
		15 Carbon housing	→ - - 1 - - -	- - - - 1 - - - - - - - 1 - - - -	3		
		16 Replacement of pump parts	→ - - - 1 - -	- - - - 1 - - - - - - - 1 - - - -	3		
		17 oil Seal steel bush	→ - - - 1 - -	- - - - - 1 - - - - - - - 1 - - -	3		
		18 Guide vane	→ - - - 1 - -	- - - - - 1 - - - - - - - 1 - - -	3		
		19 Impeller shell moulded with Chrome	→ - - - - 1 -	- - - - - 1 - - - - - - - 1 - - -	3		
		20 Discharge outlet (D.O)	→ - - - - 1 -	- - - - - - 1 - - - - - - - 1 - -	3		
		21 steel bush (D.O steel bush)	→ - - - - - 1	- - - - - - 1 - - - - - - - 1 - -	3		
		22 pump Shaft	→ - - - - - 1	- - - - - - - 1 - - - - - - - 1 -	3		
		23 non return valve	→ - - - - - 1	- - - - - - - 1 - - - - - - - 1 -	3		
		24 Cable Guard	→ - - - - - -	- - - - - - - - 1 - - - - - - - 1	3		
		25 Brass filter	→ - - - - - -	- - - - - - - - 1 - - - - - - - 1	3		
		26 Re-erection charges	→ - - - - - -	1 - - - - - - - - 1 - - - - - - -	3		

Number Present M / Daily E

Initials M / E

Left No. on Roll at end of month

No. of Working days

Average attendance during the month

No. on roll during month

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE:.....

SECTION.....PLACE.....

FOR THE MONTH OF..OCTOBER.....2022

(3)

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
			(4)									(5)									(6)								(7)								
6		Transportation of pumping machines	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
7		Labour charges	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
8		Repairs to motors	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
9		Replacement of motor parts	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
10		Rotor	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
11		upper flange	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
12		lower flange	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
13		upper Housing	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
14		Lower Housing	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
15		Carbon Housing	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
16		Replacement of pump parts	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
17		oil seal steel bush	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
18		Guide vane	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4		
19		Impeller shell moulded with bronze	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	3		
20		Discharge outlet (D.O)	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	3		
21		steel bush (D.O steel bush)	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	3		
22		pump shaft	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3		
23		Non return valve	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3		
24		Cable Guard	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	3		
25		Install filter	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	3		
26		Re-erection charges	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	3		

Number Present M Daily T.	
Initials M E	

No. on roll at the beginning of month | Admitted during the month | Left No. on Roll at end of month

No. of Working days | Average attendance during the month | No. on roll during month

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE:.....

SECTION.....PLACE.....

FOR THE MONTH OF...NOVEMBER...2022

(4)

S. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
							(5)									(7)												(10)									
6		Transportation of pump on hand cart	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
7		Labour charges	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
8		Repairs to motors	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-			3			
9		Replacement of motor parts	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-			3			
10		Rotor	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-				3			
11		upper flange	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-					3			
12		lower flange	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-					3			
13		upper Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
14		lower Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
15		Carbon Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
16		Replacement of pump parts	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
17		oil seal steel bush	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						2			
18		Guide vane	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						2			
19		Impeller shell moulded with bronze	1	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
20		Discharge outlet (D.O)	1	-	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
21		steel bush (D.O steel bush)	-	1	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
22		pump shaft	-	1	-	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
23		non return valve	-	-	1	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
24		Cable Guard	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
25		Brass filter	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			
26		Re-erection charges	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1						3			

Number Present M / Daily F																																				
Initials M / F																																				

No. on roll at the beginning of month | Admitted during the month | Left No. on Roll at end of month | No. of Working days | Average attendance during the month | No. on roll during month

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE:.....

SECTION.....PLACE.....

FOR THE MONTH OF...DECEMBER...2022

(5)

S/S	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
									(11)									(12)												(13)							
6		Transportation of pump machine	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
7		Labour charges	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
8		Repairs to motors	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
9		Replacement of motor parts	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3			
10		Rotor	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3			
11		upper flange	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
12		lower flange	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
13		upper Housing	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
14		Lower Housing	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
15		Carbon Housing	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
16		Replacement of pump parts	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
17		oil seal steel bush	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
18		Guide vane	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
19		Impeller shell moulded with bronze	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
20		Discharge outlet (D.O)	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
21		steel bush (D.O steel bush)	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
22		pump shaft	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
23		Wood return valve	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
24		Cable Guard.	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
25		Brass filter	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
26		Re-erection charges.	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
		Number Present M / Daily C.	B																																	
		Initials M / E																																		

No. on roll at the beginning of month ... Admitted during the ...

No. of Working ...

REGISTER OF ATTENDANCE & FEES

FOR THE MONTH OF...JANUARY.....2023

NAME OF THE INSTITUTE.....

SECTION.....PLACE.....

S. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
											(14)										(15)											(16)					
6		Transportation of pumping machineries	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-		3			
7		Labours charges	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-		3			
8		Repairs to motors	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-		3			
9		Replacement of motor parts	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1		3			
10		Rotor	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1		3			
11		upper flange	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
12		lower flange	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
13		upper Housing	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
14		Lower Housing	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
15		Gorloon Housing	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
16		Replacement of pump parts	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
17		oil Seal Steel bush	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
18		Guidevane	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
19		Impeller shell moulded with bronze	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
20		Discharge outlet (Do)	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
21		steel bush (Do steel bush)	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
22		pump shaft	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
23		arm returns valve	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
24		Cable Guard	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
25		Brass filter	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			
26		Re-erection charges	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-		3			

Number Present M
Daily F
Initials M

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE:.....

SECTION.....PLACE.....

FOR THE MONTH OF..FEBRUARY....2023

(7)

S.No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs. Ps.	Date of payment
											(17)									(18)																
6		Transportation of pump parts	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	—		2	✓	
7		Labour charges	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	—		2	✓	
8		Repairs to motors	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	—		2	✓	
9		Replacement of motor parts	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	—		2	✓	
10		Rotar	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	—		2	✓	
11		upper flange	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	—		3	✓	
12		Lower flange	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	—		3	✓	
13		upper Housing	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	—		3	✓	
14		Lower Housing	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	—		3	✓	
15		Carbon Housing	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	—		3	✓	
16		Replacement of pump parts	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	—		3	✓	
17		oil Seal steel bush	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	—		3	✓	
18		Guidevane	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	—		3	✓	
19		Impeller shell moulded with bronze	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	—		3	✓	
20		Discharge outlet (D.O)	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	—		3	✓	
21		steel bush (D.O steel bush)	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	—		3	✓	
22		pump shaft	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	—		3	✓	
23		non-return valve	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	—		3	✓	
24		Cable Guard	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	—		3	✓	
25		Drum filter	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	—		3	✓	
26		Re-erection charges	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	—		3	✓	

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE.....

FOR THE MONTH OF....MARCH.....2023

SECTION.....PLACE.....

Sl. No.	Admission No.	NAMES	1 2 3 4 5 6 7 8 9 10 11 12 (19)	13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 (20) (21)	No. of days present	FEES Rs. Ps.	Date of payment
6		Transportation of pump gaarches.	1 - - - - - - - - - - -	1 - - - - - - - - - - - - - 1 - - - - -	3		
7		Labour charges	1 - - - - - - - - - - -	- 1 - - - - - - - - - - - - 1 - - - -	3		
8		Repairs to motors	- 1 - - - - - - - - - -	- - 1 - - - - - - - - - - - 1 - - -	3		
9		Replacement of motor parts	- - 1 - - - - - - - - -	- - - 1 - - - - - - - - - - 1 - -	3		
10		Rotor	- - 1 - - - - - - - - -	- - - 1 - - - - - - - - - - 1 - -	3		
11		upper flange	- - - 1 - - - - - - - -	- - - - 1 - - - - - - - - - 1 - -	3		
12		Lower flange	- - - 1 - - - - - - - -	- - - - 1 - - - - - - - - - 1 - -	3		
13		upper Housing	- - - 1 - - - - - - - -	- - - - - 1 - - - - - - - - 1 - -	3		
14		Lower Housing	- - - - 1 - - - - - - -	- - - - - 1 - - - - - - - - 1 - -	3		
15		Carbon Housing	- - - - 1 - - - - - - -	- - - - - - 1 - - - - - - - 1 - -	3		
16		Replacement of pump parts	- - - - - 1 - - - - - -	- - - - - - 1 - - - - - - - 1 -	3		
17		oil seal steel bush	- - - - - 1 - - - - - -	- - - - - - - 1 - - - - - - - 1	2		
18		Guide vane	- - - - - - 1 - - - - -	- - - - - - - 1 - - - - - - - -	2		
19		Impeller shell moulded with bowl	- - - - - - - 1 - - - -	- - - - - - - - 1 - - - - - - -	2		
20		Discharge outlet (D.O)	- - - - - - - - 1 - - -	- - - - - - - - - 1 - - - - - -	2		
21		steel bush (D.O steelbush)	- - - - - - - - - 1 - -	- - - - - - - - - - 1 - - - - -	2		
22		pump shaft	- - - - - - - - - - 1 -	- - - - - - - - - - - 1 - - - -	2		
23		Non return valve	- - - - - - - - - - - 1	- - - - - - - - - - - - 1 - - -	2		
24		Cable Guard	- - - - - - - - - - - 1	- - - - - - - - - - - - - 1 - -	2		
25		Brass Filter	- - - - - - - - - - - 1	- - - - - - - - - - - - - - 1 -	2		
26		Re-erection charges.	- - - - - - - - - - - 1	- - - - - - - - - - - - - - - 1	2		

Number Present M / Daily F							
Initials M / F							

No. on roll at the beginning of month | Admitted during the month | Left No. on Roll at end of month | No. of Working | Average attendance during the month | No. on roll during month

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಜಲಮಂಡಳಿ, ಬೆಂಗಳೂರು-106

REGISTER OF ATTENDANCE & FEES

FOR THE MONTH OF.....APRIL.....2023

NAME OF THE INSTITUTE.....

SECTION.....PLACE.....

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
							23											25									31										
6		Transportation of pumping sets	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
4		labour charges	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
3		Repairs to motors	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-		3			
		Replacement of motor parts	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-		3			
0		Rotor	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-		3			
1		upper flange	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
2		Lower flange	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
3		upper Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
4		Lower Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
5		Column Housing	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
6		Replacement of pump parts	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-		3			
7		oil seal steel bush	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-		-	-	-		2			
8		Guide vane	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-		3			
9		Impeller shell molded with bronze	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-		3			
0		Discharge outlet (DO)	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-		3			
1		Steel bush (Do steel bush)	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-		3			
2		pump shaft	-	-	1	-	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
3		non return valve	-	-	1	-	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-		3			
1		Cable Guard	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-		3			
-		Brass filter	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-		3			
		Re-erection charges	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-		3			

Number Present M
Daily E

Initials M
E

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಎಂಜಿನಿಯರ್
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬೆಂಗಳೂರು-106

No. on roll during month

REGISTER OF ATTENDANCE & FEES

NAME OF THE INSTITUTE: .....

FOR THE MONTH OF ..... MAY 2023

SECTION ..... PLACE .....

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
							(25)											(25)											(27)									
6		Transportation of spray machines	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	3	✓		
7		Labour charges	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	3	✓		
8		Repairs to motors	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3	✓		
9		Replacement of motor parts	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3	✓		
10		Rotor	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	3	✓		
11		upper flange	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	3	✓		
12		Lower flange	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	3	✓		
13		upper Housing	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	4	✓		
14		Lower Housing	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	4	✓		
15		Carbon Housing	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
16		Replacement of pump parts	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
17		oil seal steel bush	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
18		Guidevane	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
19		Impeller shell moulded with bronze	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
20		Discharge outlet (D.O)	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
21		steel bush (D.O steel bush)	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
22		pump shaft	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
23		non return valve	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
24		Cable Guard	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
25		Brass fitter	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		
26		Re-erection charges	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	✓		

Number Present M
Daily F

Initials M
F

No. of Working days

Average ... during the month

No. on roll during month

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಉಪವಿಭಾಗ,
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬೆ.ಜ.ಮ.ಪ. ಬೆಂಗಳೂರು-106.

REGISTER OF ATTENDANCE & FEES

FOR THE MONTH OF.....JUNE.....2023

NAME OF THE INSTITUTE .....

SECTION.....PLACE.....

No.	NAMES	1 2 3 4 5 6 7 8 9 10 11 12	13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31	No. of days present	FEES Rs. Ps.	Date of payment
		(28)	(29) (30)			
	Transportation of pump motor set	- - - 1 - - - - - - - -	- - - - 1 - - - - - - - - - - - - - 1 -	3		
	Labour charges	- - - 1 - - - - - - - -	- - - - 1 - - - - - - - - - - - - - 1 -	3		
	Repairs to motors	- - - - 1 - - - - - - -	- - - - - 1 - - - - - - - - - - - - 1	3		
	Replacement of motor parts	- - - - - 1 - - - - - -	- - - - - 1 - - - - - - - - - - - -	2		
	Rotor	- - - - - - 1 - - - - -	- - - - - - 1 - - - - - - - - - - -	2		
	upper flange	- - - - - - - 1 - - - -	- - - - - - - 1 - - - - - - - - - -	2		
	lower flange	- - - - - - - - 1 - - -	- - - - - - - - 1 - - - - - - - - -	2		
	upper Housing	- - - - - - - - - 1 - -	- - - - - - - - - 1 - - - - - - - -	2		
	Lower Housing	- - - - - - - - - 1 - -	- - - - - - - - - 1 - - - - - - - -	2		
	Carbon Housing	- - - - - - - - - - 1 -	- - - - - - - - - - 1 - - - - - - -	2		
	Replacement of pump parts	- - - - - - - - - - 1 -	- - - - - - - - - - 1 - - - - - - -	2		
	oil seal stel bush	- - - - - - - - - - - 1	- - - - - - - - - - - 1 - - - - - -	3		
	Guide vane	- - - - - - - - - - - 1	- - - - - - - - - - - 1 - - - - - -	3		
	Impeller shell molded with bronze	- - - - - - - - - - - 1	- - - - - - - - - - - 1 - - - - - -	3		
	Discharge outlet (DO)	1 - - - - - - - - - - -	1 - - - - - - - - - - - 1 - - - - -	3		
	stel bush (DO stel bush)	1 - - - - - - - - - - -	1 - - - - - - - - - - - 1 - - - - -	3		
	pump shaft	- 1 - - - - - - - - - -	- 1 - - - - - - - - - - 1 - - - -	3		
	non return valve	- 1 - - - - - - - - - -	- 1 - - - - - - - - - - 1 - - - -	3		
	Cable Guard	- - 1 - - - - - - - - -	- - 1 - - - - - - - - - 1 - - -	3		
	Drain filter	- - 1 - - - - - - - - -	- - 1 - - - - - - - - - 1 - - -	3		
	Re-erection charges	- - 1 - - - - - - - - -	- - - 1 - - - - - - - - 1 - -	3		

Rs

Rs

Rs

Number Present M
Daily E

Initials M
E

No. on roll at the beginning of month | Admitted during the month | Left No. on Roll at end of month | No. of Working days | Average attendance during the month | No. on roll during month

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ಯಾಂತ್ರಿಕ ಗುತ್ತಿಗೆದಾರರ ಉಪವಿಭಾಗ,
ಜೆ.ಜೆ.ಎಂ.ಪಿ, ಹೊಸಪೇಟೆ-೧೦೬

REGISTER OF ATTENDANCE & FEES

FOR THE MONTH OF ..... JULY 2023

NAME OF THE INSTITUTE .....

SECTION ..... PLACE .....

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	FEES Ps.	Date of payment
6		Transportation of pump mechanicals	-	-	-	-	-	-																											-			
7		Labour charges	-	-	-	-	-	-																											-			
8		Repairs to motors	-	-	-	-	-	-																											-			
9		Replacement of motor parts	-	-	-	-	-	-																											-			
10		Rotor	1	-	-	-	-	-																											-			
11		upper flange	1	-	-	-	-	-																											1			
12		Lower flange	-	1	-	-	-	-																											1			
13		upper housing	-	1	-	-	-	-																											1			
14		Lower Housing	-	1	-	-	-	-																											1			
15		Carbon Housing	-	-	1	-	-	-																											1			
16		Replacement of pump parts	-	-	1	-	-	-																											1			
17		oil Seal Steel bush	-	-	1	-	-	-																											1			
18		Guide vane	-	-	-	1	-	-																											1			
19		Impeller shell moulded with Inserts.	-	-	-	1	-	-																											1			
20		Discharge outlet (D.O)	-	-	-	1	-	-																											1			
21		steel bush (D.O steel bush)	-	-	-	1	-	-																											1			
22		pump Shaft	-	-	-	-	1	-																											1			
23		non return valve	-	-	-	-	1	-																											1			
24		cable Guard	-	-	-	-	-	1																											1			
25		Brass filter	-	-	-	-	-	1																											1			
26		Re-erection charges	-	-	-	-	-	1																											1			

Number Present M / Daily F

Initials M / E

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಎಂಜಿನಿಯರ್
ಯಲಹಂಕ ಉಪವಿಭಾಗ,
ಜೆ.ಜೆ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

No. on roll at the beginning of month | Admitted during the month | Struck off on roll at end of month

No. of Working days | Average attendance during the month | No. on roll during month